



Dominion

DAM INSPECTION CHECKLIST POSSUM POINT POWER STATION POND ABC

INSPECTION DATE: JANUARY 12, 2016

WEATHER: 36, MOSTLY CLOUDY

INSPECTED BY: K. ACREE

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	N	0826 - NO STANDING WATER AGAINST SAND BAGS.
Erosion	N	N	SAND BAGS AND RIPRAP ARE IN PLACE, AND THERE SEVERAL SAND BAGS THAT HAVE BEEN RIPPED.
Low Point, B dike*			
Flow	N	N	0822 - NO STANDING WATER AGAINST SAND BAGS. SAND BAGS ARE IN PLACE WITH SEVERAL BAGS BEING RIPPED.
Erosion	N	N	
Outfall			
water surface El. (top of stoplogs to water)			0807 - NO STANDING WATER AGAINST WEIR & WEIR IS DRY.

* See figure below.

Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.):

- LOW POINT, C DIKE - SAND BAGS DO NOT HAVE STANDING WATER AGAINST THEM, AND SEVERAL SAND BAGS ARE RIPPED, AND SAND BAGS ARE IN PLACE.
- STANDING WATER PRESENT ON EMBANKMENT, AS NOTED ON DRAWING BELOW.
- STANDING WATER IS PRESENT AT THE TOE OF EMBANKMENT, WITHIN POND A. (TYPICAL OF PONDS B AND C, AS WELL)

